

419 Fifth Street, Suite 2100 Defiance, OH 43512 Phone 419-782-6211 architects@beilharzinc.com June 25, 2025

STATE BANK Interior Alterations Napoleon, Ohio

C5-5034

## ADDENDUM 2

This Addendum becomes a part of the Contract Documents and modifies them only to the extent herein set forth. Bidders shall acknowledge receipt of this Addendum on the Bid Form. Each bidder is responsible for distribution of information conveyed by this Addendum to its subbidders and suppliers.

Attachments: Banking Equipment Cut Sheet

Bid Question Log #1


## ITEM NO. 1: Available Information

Information on the Owner-provided banking equipment is attached for reference.

## **ITEM NO. 2:** Sheet A-101 – Door Schedule

Delete Hdw. Set column.

END OF ADDENDUM





419 Fifth Street, Suite 2100 Defiance, OH 43512 Phone 419-782-6211 architects@beilharzinc.com

June 25, 2025

STATE BANK Interior Alterations Napoleon, Ohio

C5-5034

## **BID QUESTION LOG #1**

The following questions and answers are distributed for supplemental information and clarification, and are not part of the Contract Documents. Questions answered by Addendum items are not necessarily repeated in this document.

- Q1. Project award is stated to be within 30 days of the bid. Is this calendar days or business days? Trying to determine and approximate schedule duration
  - A. Refer to General Conditions A201-8.1.4, which defines "day" as calendar day unless specifically indicated.
- Q2. Is the project required to be prevailing wage?
  - A. No.
- Q3. What is the current drive thru window size and the size of the new night depository? Would like to get a better idea of what masonry patching is going to be required for this. An allowance for this masonry work could be provided is desired.
  - A. Existing dimensions may be field measured. Coordinate requirements for new equipment with Owner.
- Q4. Was a hazardous material survey completed and a report available? Is the sub ceiling above the current ACT suspected to be asbestos? Is the VCT and adhesive suspected to be asbestos?
  - A. No hazardous materials are known to be present.
- Q5. Is GPRS required before trench cutting can occur?
  - A. GPRS may be utilized at Contractor's option.
- Q6. Is the State Bank signage behind the teller desk owner provided, contractor installed?
  - A. Refer to Section  $01\ 1000 2.01$ .A.
- Q7. Equipment that is provided by the owner, eg. Banking equipment, appliances, etc. to be installed by the general contractor?
  - A. Refer to Section 01 1000 2.01.A.

- Q8. On the mechanical print, shown on the demo section, it shows an exhaust grill in the bathroom. Then on the install section it calls out XEF-1 and shows a wall louver. Is this existing one to remain or is the engineer wanting a new exhaust fan and a wall louver added. If yes, is there a spec on the fan. We cannot find one.
  - A. This is existing to remain.

END OF BID QUESTION LOG #1